

BULLETIN NO: 15 RELEASE DATE: 3rd March 2020

Have the “Time Team” arrived in Yorvik Road?

Monday 2nd March: A new week, a new month and 43 York Road is now slightly resembling an archaeological dig site! However, Tony Robinson hasn't been spotted yet, but if we did locate an Anglo-Saxon coin that would certainly help the building fund! Suddenly demarcation lines are appearing, and a grid of foundation trenches are giving us our first visual clues to the actual perimeter of the worship hall.



Our previous building as we all know was a prefabricated construction and as such it was adequate to locate it on a solid concrete slab. The new church is a conventional building (and a lot taller) which means deep, solid foundations.

The trenches are excavated, the concrete is poured in and then the threaded studs that will secure the steel “H” section girders are set in place. These precisely located, square four stud zones give us a foresight of the perimeter of our new worship hall.

In our picture above we have highlighted one of the lines of these stud plates. This line denotes the right-hand side of the steelwork girder frames which is in fact on the left as you enter the foyer. You can clearly see the distance between the Phase One building and the girders which represents the width of the foyer area.